



# SAFETY RECALL

IMPORTANT REPAIR INFORMATION FROM GEHL FOODS, INC.  
REGARDING HOT TOP2 CHEESE AND CHILI SAUCE DISPENSERS.  
THE DISPENSER FAN BLADE MAY COME INTO CONTACT WITH THE  
HEATING COIL, POSING A FIRE AND BURN HAZARD TO CONSUMERS.

Gehl Foods recently became aware of a potential issue affecting dispenser models HT2-04 Single, HT2-04 Dual and HT2-03 APS. Dispensers with the following serial numbers are included in this recall: HT2 164500 through HT2 299689. Because we take the safety and satisfaction of our customers very seriously, Gehl's initiated a voluntary recall in cooperation with the Consumer Product Safety Commission.

**If your dispenser Serial Number does not fall between HT2 164500 and HT2 299689 it is not included in this recall and no action is needed.**

**Do not leave a dispenser operating without the lid and valve guard in place.**

Please follow these simple steps to obtain your free repair:

## Step One

Log on to **[www.gehlsafety.com](http://www.gehlsafety.com)**.  
Or call Gehl's Recall Hotline at 1-877-440-4008  
8:00 am - 4:30 pm CT, Monday - Friday



The serial # is  
located on the  
back of your  
dispenser.

## Step Two

You will be asked for  
your serial number and  
zip code, and to verify  
your address

## Step Three

Choose the repair option that works best for you:

**Option 1:** Request a free repair kit. You will receive parts and instructions within six business days. **It should take you less than 30 minutes to make the repair.**

**Option 2:** Request from Gehl's a return box and prepaid UPS label. Ship your dispenser back to Gehl's for repair. **You will have your repaired dispenser within three weeks.**